

**SECRET****PRIORITY**

P 062056Z FEB 69

FM NPIC WASHDC

TO RHCOAAA/SAC OFFUTT AFB OMAHA NEB

RHCOAAA/544TH ARTW OFFUTT AFB OMAHA NEB

RUCLFGA/100TH SRW OL 19 MCCOY AFB FLA

RUWJDBA/100TH SRW DAVIS MONTHAN AFB ARIZ

RUEBJRA/NAVRECONTECHSUPPCEN SUITLAND MD

RUEAIIA/CIA WASH DC

RUEOJFA/DIA

RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF

RUEFHQA/HQS USAF

BT

S E C R E T CITE NPIC 5611.

SAC FOR DIR, DOSR, DISD; 15TH AF FOR DI. DO; 100TH SRW FOR CO, DCOI; HQ USAF FOR [ ] DIA FOR DIAXX-2.

FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

SUBJECT: EVALUATION OF GLASS LAMP MISSION G-068

1. IMAGE QUALITY: THE OVERALL IMAGE QUALITY OF THIS MISSION IS GOOD. THE GROUND RESOLUTION AND INTERPRETATION SUITABILITY ARE GOOD. CLOUD COVER OBSCURES APPROXIMATELY 30 PERCENT OF THE ENTIRE

PAGE 2 RUEADJU 0018 S E C R E T MISSION.

## 2. MISSION DATA:

A. THE STANDARD "B" CONFIGURATION CAMERA, UNIT NUMBER 10, WAS EMPLOYED FOR MISSION G-068 FLOWN ON 4 FEBRUARY 1969. MODE 5 WAS USED THROUGHOUT THE MISSION.

B. FILM TYPE 3401 WAS USED WITH AN EXPOSURE OF 1/415 AT F/11. THE MATERIAL WAS PROCESSED TO AVERAGE GAMMAS OF 2.13 (LEFT SIDE) AND 2.14 (RIGHT SIDE). PROCESSING WAS ACCOMPLISHED BY THE NAV RECON TECH SUPPCEN.

## 3. ORIGINAL NEGATIVES:

A. EXPOSURE ADEQUATE THROUGHOUT THE MISSION.

B. DENSITY AND CONTRAST: GENERALLY MEDIUM WHERE NOT AFFECTED BY ATMOSPHERICS.

## C. IMAGE DEGRADATIONS:

(1) 9R SIDE: NEEDLE POINT SHAPED FOG PATTERNS, BELIEVE TO BE ASSOCIATED WITH CAMERA STARTUP, ARE PRESENT ON FRAMES 1, 6, 9, AND 13.

(2) 9L SIDE: PROCESSING STREAKS ARE PRESENT INTERMITTENTLY THROUGHOUT THE MISSION.

(3) BOTH SIDES: THE LAST THREE FRAMES OF THE MISSION CONTAIN FOG PATTERNS ASSOCIATED WITH CAMERA SHUTDOWN.

DISTRIBUTION	
CY	OFFICER 25X11
1	FILE
	CABLE SEC.
	PP&B/RD
	SECURITY
	PSG/OC
	NRD
	REFRO
	AID
	ISS
	PRMD
	SCLEN
	WEST
	EAUT
	M&S
	PCM
	IAS
	DIA-XX4
	SPAD
	DIA-AP
	25X1
	CMX

ADVANCE CY  
SANITIZED  
WITH TEXT

PAGE 3 RUEADJU 0018 S E C R E T

## D. PHYSICAL DEGRADATIONS:

(1) 9R SIDE: TWO HEAT SPLICES ARE PRESENT ON THIS MISSION.

(2) 9L SIDE: A MANUFACTURING SPLICE AND TWO HEAT SPLICES ARE PRESENT ON THIS MISSION. THE MATERIAL WAS CUT IN FRAME 279 DUE TO A PROCESSING ANOMALLY.

E. AUXILIARY DATA: THE COUNTER HELD A PLUS SIX BIAS THROUGHOUT THE MISSION. ALL OTHER DATA RECORDING SYSTEMS FUNCTIONED PROPERLY.

F. THE LAST TITLED FRAME IS 1825 (RIGHT SIDE, A PARTIAL FRAME) AND 1823 (LEFT SIDE).

4. POSITIVES: THE PRINTING AND PROCESSING ARE GOOD.

GP-1

S E C R E T

---END OF MESSAGE---

**SECRET**

GROUP 1  
Excluded from automatic  
downgrading and  
declassification